

Fire Door Focus

Safety and lives first.

A ONE-PAGE GUIDE - FIRE DOOR INSTALLATION

A certified door fitted wrong is still a failed door

Around 80% of fire doors in UK buildings are reportedly fitted or maintained incorrectly – and installation is where that gap begins. A doorset fitted with the wrong gaps, the wrong intumescent protection or mismatched parts will not perform as tested in the one moment it has to.

Certified, matched, tested as a system (FD30 / FD60)

A fire door is a complete system – leaf, frame, hinges, closer, seals, glazing and ironmongery – tested together to hold back fire for 30 (FD30) or 60 (FD60) minutes. Swap a component or fit outside tolerance and that rating no longer applies.

Where wrong fitting fails

Excessive gaps, missing or damaged intumescent strips, packers in the wrong place, or a closer that will not pull the door onto its latch all break compartmentation. We remediate before we replace – repairing where it is safe and compliant, and fitting new certified doorsets through accredited master carpenters where it is not.

Certified work, certified on the day

UK Fire Door Training certified, Citation approved and fully insured across Cornwall and Devon, with same-day digital certification on every job via our Proprietary 'Still Standing' App. Install is one of four joined-up services – Inspect, Install, Certify, Maintain.

BY THE NUMBERS

Around 80% of fire doors in UK buildings are reportedly fitted or maintained incorrectly – installation quality is where that gap begins.

Arrange certified fire door installation – 07815 196117